


## EPA Notification of Hazardous Waste Site

TXS-000-001-190000325



This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

JUN 10 1981

6AEP

## A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Sou. Pac. Trans. Co. Wood Preserving Works

Street PO Box 1319

City Houston

State Tx. Zip Code 77001

## B Site Location: TXD-98-062-5446

Enter the common name (if known) and actual location of the site.

Name of Site SPT Co. Wood Preserving Works

Street 4910 Liberty Road

City Houston County Harris State Tx. Zip Code 77026

## C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Lane, M. A., Supt.

Phone (713) 223-6582

## D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 2-1-80 To (Year) 10-17-80

## E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

## General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☐ Organics
2. ☐ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☐ Acids
7. ☐ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

## Source of Waste:

Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

## Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

U188
U051
K001



SUPERFUND FILE

FEB 22 1993

REORGANIZED

U051 - Creosote

U188 - Phenol

K001 - bottom sediment sludge

WASTE WATER TREATMENT

creosote/ or pentachlorophenol



Notification of Hazardous Waste Site		Side Two
<b>F Waste Quantity</b>	<b>Facility Type</b>	<b>Total Facility Waste Amount</b>
Place an X in the appropriate boxes to indicate the facility types found at the site.	1. <input type="checkbox"/> Piles.	cubic feet <u>36,000</u> Impoundment
In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.	2. <input type="checkbox"/> Land Treatment.	gallons _____
In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.	3. <input type="checkbox"/> Landfill	<b>Total Facility Area</b>
	4. <input type="checkbox"/> Tanks	square feet <u>32,000</u>
	5. <input checked="" type="checkbox"/> Impoundment	acres _____
	6. <input type="checkbox"/> Underground Injection	
	7. <input type="checkbox"/> Drums, Above Ground	
	8. <input type="checkbox"/> Drums, Below Ground	
	9. <input type="checkbox"/> Other (Specify) <u>Process drippings from operation</u>	

**G. Known, Suspected or Likely Releases to the Environment:**

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

**H. Sketch Map of Site Location: (Optional)**

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

**I. Description of Site: (Optional)**

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Holding basin established 2-1-80 to contain material accumulated by a clean up program. Basin was closed from receiving additional waste 10-17-80. Texas Department of Water Resources issued revised Solid Waste Registration No. 31547 to cover this facility. Incidental drippings from operations over time may have caused other contamination.

**J. Signature and Title:**

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name M. A. Lane ☐ Owner, Present  
 Street PO Box 1319 ☐ Owner, Past  
 City Houston State Tx. Zip Code 77001 ☐ Transporter  
 Signature [Signature] ☒ Operator, Present  
 Date 5-27-81 ☒ Operator, Past  
☐ Other